

Approved For Release 2005/04/22 : CIA-RDP85B00803R000100030045-2

29 Oct 1959 DPD-7417-59

25X1

[redacted] visited VAFB with Hqs and Contractor group to accept and inspect components for Flt 1051 and to review film handling, preflight procedures at L Bldg. VAFB.

The unit completely configured for preflight check--this had not been done by BMD crew heretofore. [redacted] found no one in the ground crew who had sufficient background or experience to adequately prepare aerial photographic equipment for flight. Furthermore, the "clean room" for preflighting was more like a factory work space--sadly lacking in cleanliness and equipment to assist in loading the payload. Film handling procedures were incorrect and had already led to damaging of spools and fogging of film.

25X1

He recommended Proj, LMSD, BMD coordinate on acceptable procedures for an acceptance check of the system; that a photo technician be added to the preflight crew at VAFB L Bldg.; and better procedures be established; further air conditioning of the preflight area and film storage area be done; and that monthly inspection visits by Hqs, EKC and LMSD reps to L Bldg. be made to keep watch over compliance with procedures.

NRO review(s) completed.